

EAST Search History

Ref #	Hits	Search Query	DBs	Default Operator	Plurals	Time Stamp
L3	3992	375/316	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2006/12/07 14:28
L4	32	"375239"	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2006/12/07 14:54
L5	515	375/239	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2006/12/07 15:14
L6	3007	375/295	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2006/12/07 14:54
L7	2032	375/343	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2006/12/07 15:22
L8	3817	375/354	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2006/12/07 15:22
L9	7	demodulat\$3 same squar\$3 near (in adj phase I) same squar\$3 near (quadrature Q)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2006/12/07 15:38
L10	156	squar\$3 near (in adj phase I) and squar\$3 near (quadrature Q) not L9	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2006/12/07 15:38

EAST Search History

L11	129	squar\$3 near (in adj phase I) same squar\$3 near (quadrature Q)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR .	ON	2006/12/07 15:38
L12	34	squar\$3 near (in adj phase I) and squar\$3 near (quadrature Q) not L9 not L11	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2006/12/07 15:44
L13	34	squar\$3 near (in adj phase I) and squar\$3 near (quadrature Q) not L9 not L11	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2006/12/07 15:53
S1	7	demodulat\$3 same squar\$3 near (in adj phase I) same squar\$3 near (quadrature Q)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2006/12/06 21:13
S2	129	squar\$3 near (in adj phase I) same squar\$3 near (quadrature Q)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR .	ON	2006/12/06 21:19
S3	122	squar\$3 near (in adj phase I) same squar\$3 near (quadrature Q) not S1	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2006/12/07 15:38

12/7/2006 4:04:33 PM C:\Documents and Settings\efile\My Documents\EAST\Workspaces\10677753.wsp



Welcome United States Patent and Trademark Office

.. □ Search Session History

BROWSE

Edit an existing query or

compose a new query in the Search Query Display.

Select a search number (#) to:

- · Add a query to the Search Query Display
- Combine search queries using AND, OR, or NOT
- · Delete a search
- Run a search

	••	•	_	۰

SEARCH

IEEE XPLORE GUIDE

SUPPORT

Thu, 7 Dec 2006, 3:20:18 PM EST

Search Query Display



WER 1.1	1.54 GR
1)E 13 34 14 1	1 4 4

Recent Search Queries		Results
<u>#1</u>	(((squaring <or>squared<or>square<and>in phase) <and>quadrature<and>multiplying) <and> (pyr >= 1950 <and> pyr <= 2002)<in>metadata)</in></and></and></and></and></and></or></or>	2563
<u>#2</u>	((squaring <or>squared<or>square<and>in phase) <and>quadrature) <and> (pyr >= 1950 <and> pyr <= 2002)</and></and></and></and></or></or>	9046
#3	((squaring in phase <and>squaring quadrature)) <and> (pyr >= 1950 <and> pyr <= 2002)</and></and></and>	0
<u>#4</u>	((squaring in phase <and>squaring quadrature)) <and> (pyr >= 1950 <and> pyr <= 2002)</and></and></and>	0
<u>#5</u>	((in phase squared <or> i squared<and>quadrature squared<or>q squared)) <and> (pyr >= 1950 <and> pyr <= 2002)</and></and></or></and></or>	102



Help Contact Us Privacy & Security IEEE.org © Copyright 2006 IEEE - All Rights Reserved

indexed by in Inspec